

PRINTMAKING STUDIO INSPECTION REPORT JANUARY 2014

This report focuses on creating a safe, non-toxic printmaking studio wherever possible.

INTAGLIO:



Both the 28 and 18 inch presses in Room 403 are in good working condition. The beds are free of nicks or marks that would effect printing, and move freely with the gear driven spindle. The rollers are free of damage.



Neither press possesses a scale to determine the exact amount of pressure between the bed and the roller. This can be an issue if one side of the roller is lowered significantly more than the other, creating potential for stripping of the threads as seen in the photograph.

SOLUTION:

Clearly communicated signage will be installed to ensure that students do not strip the threads on the adjustment gauges.